



Case Study – Guano & Mould Cleaning

Removing guano and mould from a residential property.



Summary

Client's Problem: Contaminated loft space after pigeons entered the roof space via a hole in the roof, water ingress from rain.

Location: Portsmouth.

How Long it Took: 2 days.

What Machinery was Used?

- HEPA vac
- Appropriate PPE
- Plant based cleaning solutions

What Safety Precautions Were Taken?

Following all works surface and air sampling was undertaken to ensure that the internal environment was at a safe and acceptable level and all associated risk 'normalised'

Guano & Mould Removal

A client got in touch with Vinci Response Services after discovering that birds had got into her attic through a hole in her roof and had left guano and feathers all over the loft. There was also mould throughout the attic which also needed cleaning.

Vinci's experienced team cleared and cleaned the loft space before undertaking guano decontamination and mould remediation. Loft insulation and other contaminated items also had to be removed and safely disposed of.

A safe method of access was required to access the loft as well as full PPE (gloves, glasses, coveralls, face masks, safety boots and head protection).

