



Case Study – Brick Paint Removal & Restoration

Paint Removal From Residential Property



Summary

Client's Problem: The home owner contacted Vinci Response to discuss the removal of red brick paint from the outside of their property. They wanted the original aesthetic and visual appeal restored.

Location: North London.

How Long it Took: 1 day.


What Equipment was Used?

- 1028NC Blast Pot *
- Sponges
- Brushes
- Window protection

** A blasting machine used to safely remove paint, corrosion and graffiti*

How we did it

- ✓ **Pre-Remediation**
Before the remediation began, some important safety and preparation work was needed. Notably, ground and window protection was put in place to ensure the removal and restoration process did not damage the property.
- ✓ **Remediation**
All surfaces covered in red paint were blasted with the 1028NC Blast Pot. This is an excellent tool that can blast surfaces without causing damage to the original structure. It is very effective at removing paint, corrosion, and graffiti.
- ✓ **Post-Remediation**
Following blasting, the bricks and mortar were checked, the ground and window protection was removed, the site was thoroughly cleaned, and the job was complete.



Before

After

